

DGT1 Zero Calibration

Switch Off unit by pressing and holding C until OFF displayed

Press C (on) then when 8888888 displayed immediately press 

F.ModE



Setup



Config



Filter50



0.CALiB



CAL.0?



Do not lean on machine whilst calibrating

then after calibration process finishes

Filter50

C
C
C

Save?



Procedure complete